

Status	2 - Disposition Needed		Trend	06-Workmanship/Needs Repair	
Department	NCSX		Division	WBS 142	
Source/Org	FABRICATION, OPERATIONS & MAINTENANCE				
Item Dwg/Part#	N/A	Procurement #	D-NCSX-MCF-004	Cost Center	
RAP#	3234	Job Doc #	D-NCSX-MCF-004	Vendor	
RAP Title Modular Coil Fabrication - Post VPI Activities					

☐ HoldTag Applied**Nonconforming Condition (include requirement(s) violated):**

MCWF-C4, During the cotton candy shell removal process, part of the post VPI operations, the "Side B, Zone 2, Outer" cooling tube was damaged. Damage consists of a break in the tube approx. 1.5" away from the winding pack, and a flattening of the tube approx. 0.25" away from where it is soldered to the copper chill plate. See attached picture for details

Lot Size Recd 0 Sample Size Insp 0 ☐ Lot Rejected # Rejected 0

Reported By Chrzanowski J Validated By Phelps C Validated Date 09/15/06

Disposition: ~~Rework*~~ ~~Repair*~~ ~~Use As Is*~~ ~~Return To Vendor*~~ ~~Scrap*~~

For rework or repair of vendor supplied equipments, fill in information below:

#Hours		\$Est Labor		\$G&A	
\$Material		\$Burden		\$Total	

Disposition By		Date	
Supervisor's Concur		Date	
Eng. Dept. Head Concur		Date	
WCO/Other		Date	

PQA/QC Mgr Dispos Concur		Date	
QC Field Verification By		Date	

Distribution

Cog J. Chrzanowski

Insp C. Phelps

Proj. Doc Control (when closed)

QC Files

Malsbury J

Boscoe J

Meighan T

Dudek L

Reiersen W

Williams M

Tyrrell M

Malinowski F

Disposition: Rework____ Repair ____ Use As Is____ Return to Vendor____ Scrap____

For rework or repair of vendor supplied equipment, fill in information below:

Hours _____ \$ Est Labor_____ \$ G&A_____

\$ Material _____ \$ Burden _____ \$ Total _____

Disposition by _____

Supervisor's Concurrence _____

Eng. Dept. Head Concurrence _____

Other (i.e., WCO/FPE) Concurrence _____

PQA/QC Mgr Disposition Concurrence _____

QA Field Verification by _____