

PPPL ENGINEERING CHANGE NOTICE (ECN) ECN # 5148

COGNIZANT INDIVIDUAL: Mike Viola	
ECN TITLE: VV Support Stand Lifting Fixture	
ASSOCIATED ECP: None	
CC/WP/Job:9450 1*** 1803	AREA OR PROJECT: NCSX

LIMITATION OF SCOPE - NOTE: A Work Planning Form is NOT required if the total change to be accomplished (ENG-032):

- Is not large or complex or does not represent a new installation into a usable space
 - Does not have a significant ES&H impact
 - Does not involve tritium or other radioactive contaminated or activated equipment
 - Does not impact multiple projects, systems, or groups
- OR does not change the scope or intent of the original design.

Responsible Line Manager CONCURRENCE: _____
 (Signature indicates that no Work Planning form is required.)

If non-concurrence or associated with a work planning form, enter the WP Number:

DRAWING(S) AFFECTED NUMBER:	NEW Revision	TITLE
SE184-001	3	VV Supt Stand Fixture Assembly
Continued on Back		

<p>DESCRIPTION OF CHANGE: (State Drawing No., Zone/Group, or List Attachments)</p> <p>SE184-001: Removed the Hoist Ring Mount Lifting Assembly and the parts pertaining to the Ratchet and Paul assembly.</p>
--

PPPL ENGINEERING CHANGE NOTICE (ECN) ECN # 5148

REASON FOR CHANGE:

The Hoist Ring Mount Lifting Assembly was found to be structurally inadequate as a lifting fixture and not needed. The Ratchet and Paul assembly did not perform properly and was found to be not needed as an additional safety mechanism with VV mounted on the support stand in a balanced condition.

ENGINEERING CHANGE PROPOSAL:

DATE: 7/6/2006

COGNIZANT INDIVIDUAL MAKING THE CHANGE:

RESONSIBLE LINE MANAGER: