
Customer: PRINCETON PLASMA PHYSICS LAB

Contact: Mike Viola
E-Mail: mviola@pppl.gov

Telephone: 609-243-3655
Fax: 609-243-2021

Part: /

Drawing ID: SE120-002

Revision: 1

Customer P.O.: S005243-F/Ln:3
Serial No./Qty: VVSA # 3

Reported By: DOUG MCCORKLE
E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: The flatness of the VV Flange Seal on half b checks 0.088 (0.038 out of tolerance).

Proposed Disposition:

SUBMITTING TO PPPL FOR REMEDIAL DISPOSITION

Number of additional pages: 0

Customer Disposition: Use As Is Rework Repair Scrap Replace

Technical Contact Approval: _____

Title: _____ **Date:** _____

Buyer Approval: _____

Title: _____ **Date:** _____

Major Tool Implemented By: _____

Title: _____ **Date:** _____

Nonconformance Report: Major Tool NC20354

This is for: **VVSA # 3 Profile** SE120-002

Problem:

The flatness of the VV Flange Seal on half b checks 0.088 (0.038 out of tolerance).

MTM Recommended Disposition:

None

Project Disposition:

Use as is.

Approvals:

Procurement Technical Representative

Responsible Line Manager: