




# Case 0918a14

Single Pack:  
7.3 x 11-cm



Double Pack:  
4 x 12-cm, 1.6-cm gap





# Problem Area "A"

Needs local adjustment of M2 winding center



# Problem Area "B"

