

---

**Customer: PRINCETON PLASMA PHYSICS LAB**

Contact: Frank Malinowski

E-Mail: [fmalinowski@pppl.gov](mailto:fmalinowski@pppl.gov)

Telephone: 609-243-2441

Fax: 609-243-2021

**Part: /SE122-112-3 (CF BLANK FLANGE)**

Drawing ID: SE122-113

Revision: 0

Customer P.O.: S005243-F

Serial No./Qty: N/A

Reported By: DOUG MCCORKLE

E-Mail: [dMcCorkle@MajorTool.com](mailto:dMcCorkle@MajorTool.com)

Telephone: 317-636-6433

Fax: 317-634-9420

Problem: Magnetic Permeability requirement 1.02 Max

Checks > 1.05, but < 1.1

---

**Proposed Disposition:**

CUSTOMER DISPOSITION REQUIRED

---

Number of additional pages: \_\_\_\_\_

---

**Customer Disposition:**     Use As Is     Rework     Repair     Scrap     Replace

**Technical Contact Approval:** \_\_\_\_\_

**Title:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Buyer Approval:** \_\_\_\_\_

**Title:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Major Tool Implemented By:** \_\_\_\_\_

**Title:** \_\_\_\_\_ **Date:** \_\_\_\_\_