NCSX Work Approval Form (WAF)

WBS Number: 161 WBS Title: LN2 Distribution System Job Number: 1601-161 Job Title: LN2 Distribution System Job Manager: Paul Goranson		
Description:	This element covers the electrical leads within the cryos (WBS 131), PF (WBS 132), External Trim (WBS 133), Work includes engineering design, procurement, and fab supports. Work in this WBS ends with the delivery of coroperations.	and Modular (WBS 14) Coils. rication of leads and associated
Schedule:	See Attached	
Approvals:	Job Manager	Date
	Responsible Line Manager	Date
	Project Manager	Date
	Engineering Department Head	Date