

## NCSX Work Approval Form (WAF)

**WBS Number: 19**

**WBS Title: Stellarator Core Management and Integration**

**Job Number: 1901**

**Job Title: Stellarator Core Management and Integration**

**Job Manager: Mike Cole**

**Description:**

WBS 191 (Stellarator Core Management) - This effort covers general management and oversight for the Stellarator Core. It is assumed to be half time for the duration of the project. This is a Level of Effort task. WBS 192 (Stellarator Core Integration and Global Analysis) - This effort covers design integration activities for the Stellarator Core, including global Pro-E models and drawings for the Stellarator Core, Pro-Intralink database maintenance of all drawings and CAD models, analyses common to all of WBS 1, and design criteria documents. This is a level of effort task.

**Schedule:**

See Attached

**Approvals:**

_____	_____
Job Manager	Date
_____	_____
Responsible Line Manager	Date
_____	_____
Project Manager	Date
_____	_____
Engineering Department Head	Date