

**NCSX Work Approval Form (WAF)**

**WBS Number: 39**

**WBS Title: Diagnostics Integration & Oversight**

**Job Number: 3901**

**Job Title: Diagnostics Integration & Oversight**

**Job Manager: Brent Stratton**

**Description:**

This WBS element consists of the physics support to provide diagnostic input through the detailed design phase of the machine. As the design of the core machine continues, it is important to continue the integration of diagnostics into the device and the NCSX facility with higher levels of definition.

**Schedule:**

See Attached

**Approvals:**

\_\_\_\_\_  
Job Manager

\_\_\_\_\_  
Date

\_\_\_\_\_  
Responsible Line Manager

\_\_\_\_\_  
Date

\_\_\_\_\_  
Project Manager

\_\_\_\_\_  
Date

\_\_\_\_\_  
Engineering Department Head

\_\_\_\_\_  
Date