

ECN-5082. Requirement originally included grooves to facilitate leak checking by vendor. However, vendor elected another means of leak checking and therefore the grooves are no longer required. Specifically, this ECN eliminated the leak checking groove on SE121-014 (Rev 1-c) and SE1221-091 (Rev 0-a) . Additionally, this ECN added a missing weld symbol to SE121-004 (Sheets 4 through 19) for joining the port extensions to the vessel (Rev 2-d).

(See ECN-5082 for details)

