

<i>NCSX RFD</i> <i>Part I</i>	Number: NCSX-RFD-14-001	RFD Description: Revised location of part number in MCWF casting
Initiator: P. Djordjevich	Organization: EIO	
List of Impacted Documents: Drawing SE-141-114 shows the reference location of the pattern/casting identification number for Type A coils.		
Cost Impact: (If none, so state) None.		
Schedule Impact: (If none, so state) None		
Impact on Interfaces with Other WBS Elements/Items: (If none, so state) None		
Full Description of the Deviation Requested: (Use continuation pages, e-mails, letter, sketches, etc. as needed and include amplifying information as appropriate to support deviation request.) Ref.: P. Djordjevich's e-mail of 29 March 05; Subject: Pattern Change deviation. "EIO would like to formally request a deviation on A coil for a re-location of pattern/casting identification number. Please review the attachment and advise. Thanks Peter". This change will simplify the pattern and mold design.		
Attachments: Attachment 1 - P. Djordjevich's e-mail of 29 March 05 Attachment 2 – The pdf drawing attached to this e-mail showing proposed alternate locations for the pattern/casting identification number.		
Initiator Signature: _____ Date: _____		

<i>NCSX RFD</i> <i>Part III</i>	Number: NCSX-RFD-14-001	RFD Description: Revised location of part number in MCWF casting
RLM: B. Nelson		Organization: ORNL
<p>RLM Recommended Disposition:</p> <p><input checked="" type="checkbox"/> Approve <input type="checkbox"/> Do Not Approve (If recommendation is to approve, ECP will be assigned)</p> <p>Additional remarks:</p> <p>The NCSX project approves EIO's request to locate the pattern/casting identification numbers for Type A coils in the alternate locations shown in Attachment 2.</p>		
<p>RLM Signature: _____</p>		
<p>Project Disposition: (Include ECP Number): ECP-028. This approved RFD will be identified in the list of approved RFD's to be included in NCSX-CSPEC-141-03-07 (which would be the next revision).</p>		

Attachment I: E-mail request:


From: Peter Djordjevich [djord@earthlink.net]
Sent: Tuesday, March 29, 2005 2:09 PM
To: Phil Heitzenroeder; PQA
Cc: NKHFlowen; royjratc-aol-com-offsite
Subject: Pattern Change deviation

EIO would like to formally request a deviation on A coil for a re-location of pattern/casting identification number.
Please review the attachment and advise.
Thanks
Peter

Peter Djordjevich
djord@earthlink.net
EarthLink Revolves Around You.

Attachment II. Proposed location change

TOTAL P.001



3176349420 P.001/001 MAR-29-2005 12:28 MAJOR TOOL