Rev 7-a: RFD-14-022 authorized reorientation of the lead slots for the Type B MCWFs (2.2° horizontal displacement at top and 0.114" vertical displacement. See RFD-14-022 for details)