

**MetalTek**

*Grandelet Division - CA / PA / RGA Database*

**Corrective Action**

**1252**

Corrective Action Type FOR CASTING DISCONTINUITIES

Date 3/24/2005

CA Originator Ruud

Pattern Number: C-1 Coil

**Description of Defect / Non-Conformance**

Major defects were observed during final Penetrant inspection.

**Root Cause**

Inherent casting discontinuities.

**Corrective Action**

Excavate discontinuities and weld repair.

**Verification of Corrective Action**


Penetrant Inspection of weld repairs.

Actual Completion and File Date: 3-24-05


Signed: CA Ruud



CC: Barry Craig, Dean Berger, E.J. Kubick, R Suria, File

APPROVED: 

25 MARCH 2005



28 March 05