

Major Tool & Machine, Inc.
1458 East 19th Street
Indianapolis, IN 46218-4289

MTM N/C: 18236

Page: 1
Date: 09/21/05
User ID: BOWLINK

Customer: ENERGY INDUSTRIES OF OHIO

Contact: NANCY HORTON
E-Mail: NKHFlowen@aol.com

Telephone: 216-496-2314
Fax: 216-328-2001

Part: SE141-116 / MODULAR COIL WINDING FORM TYPE
Drawing ID: SE141-116 Revision: 6

Customer P.O.: S005242-F/Ln:1
Serial No./Qty: C1

Reported By: KEVIN BOWLING
E-Mail: kBowling@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: AFTER MACHINING SEVERAL MACHINING DEFECTS WERE DETECTED UPON VISUAL EXAMINATION. SEE ADDITIONAL DOCUMENTS FOR MAPS AND LISTS OF (16) SEPARATE NON-CONFORMING FEATURES.


Proposed Disposition:

SUBMIT TO CUSTOMER CONTINUE PROCESSING THE PART.

Customer Disposition: Use As Is Rework Repair Scrap Replace

PAPL WILL PATCH IMPERFECTIONS WITH
FILLED EPOXY MIXTURE

Technical Contact Approval:




Title:

Tech Reps

Date:

9/22/05

RLM ~~Buyer~~ Approval:




Title:

RLM

Date:

9/22/05

Major Tool Implemented By:



Title:

PROG. MGR

Date:

23-SEP-05