

Major Tool & Machine, Inc.
1458 East 19th Street
Indianapolis, IN 46218-4289

MTM N/C: 18237

Page: 1
Date: 09/21/05
User ID: BOWLINK

Customer: ENERGY INDUSTRIES OF OHIO

Contact: NANCY HORTON
E-Mail: NKHFlowen@aol.com

Telephone: 216-496-2314
Fax: 216-328-2001

Part: SE141-116 / MODULAR COIL WINDING FORM TYPE
Drawing ID: SE141-116 Revision: 6

Customer P.O.: S005242-F/Ln:1
Serial No./Qty: C1

Reported By: KEVIN BOWLING
E-Mail: kBowling@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: AFTER MACHINING SEVERAL MACHINING DEFECTS ON THE OUTSIDE OF THE PART WERE DETECTED UPON VISUAL EXAMINATION. SEE ADDITIONAL DOCUMENTS FOR MAPS AND LISTS OF (9) SEPARATE NON-CONFORMING FEATURES.

Proposed Disposition:

SUBMIT TO CUSTOMER CONTINUE MANUFACTURING.

Customer Disposition: Use As Is Rework Repair Scrap Replace

ITEM 3 - BLEND TROUGH SMOOTHLY
ITEMS 1, 2, 4, 5, 6, 7, 8, 9 - REMOVE SHARP EDGES, GRIND FLUSH

Technical Contact Approval: [Signature]
RLM Buyer Approval: [Signature]

Title: Tech. Rep Date: 9/22/05
Title: RLM Date: 9/22/05

Major Tool Implemented By: [Signature]

Title: Prod. Mgr. Date: 26-SEP-05

n:\mtmapps\mtmnc14.qip