

## Instrument Details

Level Controller Replacement	500					
Dewpoint Controller Replacement	1400					
Temperature Controller Replacement	3100					<i>(in 1991 \$)</i>
<i>Size</i>		<i>Labor</i>	<i>Material Cost</i>	<i>Total Labor</i>		<i>M&amp;S</i>
		<i>Manhours</i>	<i>(\$)</i>	<i>(Mhours)</i>		<i>(\$)</i>

Level Controller Replacement	1	16	500	16	500
Dewpoint Controller Replacement	1	24	1400	24	1400
Temperature Controller Replacement	1	16	3100	16	3100

**For Small Quantities M&S add:10%** \$0

**TOTAL** 56 \$5,000

**ManWeeks** 1.4

M&S In FY 2003 \$ \$12,049.23

M&S \$12,100