

Major Tool & Machine, Inc.
1458 East 19th Street
Indianapolis, IN 46218-4289

MTM N/C: 19233

Page: 1
Date: 02/17/06
User ID: GRIFFITH

Customer: ENERGY INDUSTRIES OF OHIO

Contact: NANCY HORTON
E-Mail: NKHFlowen@aol.com

Telephone: 216-496-2314
Fax: 216-328-2001

Part: SE141-137 /

Drawing ID: SE141-137

Revision: 1

Customer P.O.: S005242-F/Ln:4
Serial No./Qty: 12 PCS.

Reported By: MIKE GRIFFITH
E-Mail: mGriffith@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: PER RFD 14-011 MAGNETIC PERMEABILITY TO BE NO GREATER THAN 1.03.
BEARING PLATES FOR C4, C5 AND C6 CHECK BETWEEN 1.03 AND 1.05.

Proposed Disposition:

PROPOSE TO USE AS IS.

Number of additional pages: _____

Customer Disposition: ☐ Use As Is ☒ Rework ☐ Repair ☐ Scrap ☐ Replace

The material specified for the bearing plates will be changed to Stelalloy. The bearing plates for all MCWFs except C1, C2, C3 (already been accepted by NCSX) shall be made of Stelalloy.

Major Tool Implemented By: _____ **Title:** _____ **Date:** _____

Approved by:

Tech. Rep.,

RLM