

Princeton University

**Plasma Physics Laboratory**

James Forrestal Campus

P.O. Box CN17

Princeton, N.J. 08543

31 May 2006


Ms. Nancy Horton  
Energy Industries of Ohio  
6100 Oak Tree Boulevard, Suite 200  
Independence, Ohio 44131

SUBJECT: Subcontract S005242-F  
**Type B "T" Holes**

Dear Ms. Horton:

In earlier conversations, it was noted that NCSX was reviewing the stresses in the areas of some of the Type B "T" tapped holes to determine if some holes needed to be deleted to reduce stresses. As a result of this review, some holes WILL be deleted. A revised drawing is expected to be issued by the end of the week. In the meantime, EIO is requested to not drill any of these holes.

Regards,



Larry L. Sutton

Senior Subcontract Administrator

cc: T. Brown  
P. Heitzenroeder  
F. Malinowski  
B. Simmons  
M. Tyrrell  
D. Williamson