
Customer: PRINCETON PLASMA PHYSICS LAB

Contact: LARRY SUTTON
E-Mail: S-04286-F

Telephone: 609-243-2441
Fax: 609-243-2021

Part: /SE122-104-1 PORT 12 COVER

Drawing ID: SE122-104 Revision: 1

Customer P.O.: S005243-F/Ln:9
Serial No:9/294

Reported By: DOUG MCCORKLE
E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: PER B.P. MAG. PERM. TO BE LESS THAN 1.02
PART CHECKS GREATER THAN 1.3 AND LESS THAN 1.4

Proposed Disposition:

CUSTOMER DISPOSITION REQUIRED

Number of additional pages: _____

Customer Disposition: Use As Is Rework Repair Scrap Replace

Technical Contact Approval: _____

Title: _____ **Date:** _____

Buyer Approval: _____

Title: _____ **Date:** _____

Major Tool Implemented By: _____

Title: _____ **Date:** _____

Nonconformance Report: Major Tool NC19176

This is for / SE122-104-1 PORT 12 COVER

Problem:

PER B.P. MAG. PERM. TO BE LESS THAN 1.02

PART CHECKS GREATER THAN 1.3 AND LESS THAN 1.4

Project Disposition:

Accept as is

Approvals:

Procurement Technical Representative

Art Brooks, Technical Assurance

Responsible Line Manager:

Project Quality Assurance: