
Customer: PRINCETON PLASMA PHYSICS LAB

Contact: Frank Malinowski

E-Mail: fmalinowski@pppl.gov

Telephone: 609-243-2441

Fax: 609-243-2021

Part: /SE120-004-23 (CF 6" Flange)

Drawing ID: SE120-004

Revision: 1

Customer P.O.: S005243-F

Serial No./Qty: N/A

Reported By: DOUG MCCORKLE

E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433

Fax: 317-634-9420

Problem: Magnetic Permeability required to be 1.02 Max

Parts Check >1.05 but < 1.1

Proposed Disposition:

CUSTOMER DISPOSITION REQUIRED

Number of additional pages: 0

Customer Disposition: Use As Is Rework Repair Scrap Replace

Technical Contact Approval: _____

Title: _____ **Date:** _____

Buyer Approval: _____

Title: _____ **Date:** _____

Major Tool Implemented By: _____

Title: _____ **Date:** _____