
NCSX June 2007 ETC TABLE V - Basis of Estimate

WBS Number: 181 WBS Title: FPA Planning & Design Job Number: 1806 Job Title: FPA Specs & Drawings Job Manager: Mike Cole


Machine Assembly




Attaching Ports to Vacuum Vessel



Vacuum Vessel Supports





NCSX June 2007 ETC TABLE V - Basis of Estimate

WBS Number: 181 WBS Title: FPA Planning & Design Job Number: 1806 Job Title: FPA Specs & Drawings Job Manager: Mike Cole

Man Hole Port Drawing

