## NCSX June 2007 ETC TABLE III - Fabrication/Assembly Installation

WBS Number: 135										
	lanaid Curana	m4 C4m	04							
WBS Title: Central Solenoid Support Structure										
Job Number: 1353										
Job Title: CS Support Structure Procurements										
Job Manager: Fred Da										
In-house Fabrication and Assembly and Installation										
Description: N/A Assembly covered in job 1352										
Worksheets									ı	
Labor for parts assembly should be in Job 1352  Labor for installation should be in Machine Assembly Task										
Labor for installation should be in	ask									