NCSX Work Approval Form (WAF)			
WBS Number: 821/822 WBS Title: Engineering Management and Systems Engineering Job Number: 8202 Job Title: Engineering Management and Systems Engineering Support Job Manager: Wayne Reiersen			
Description:			
	Engineering Management The Engineering Manager is responsible for the successful execution of the engineering design, fabrication, and assembly efforts. Specific responsibilities include: Risk management Paris of all specific principles in a least in		
	 Project planning, including implementing the PPPL Work Planning (WP) program Safety, including implementing the PPPL Integrated Safety Management (ISM) program Responsible Line Managers (RLMs) are responsible for managing the on-site fabrication and assembly work and the design, fabrication, and assembly of ancillary, facility, and electrical systems. Line management of the ORNL scope is part of WBS 19. 		
	Systems Engineering Support Responsibilities include: Requirements management Design verification, including a program for systematic design reviews Configuration management and change control, including processing of Requests for Deviations (RFDs), Engineering Change Proposals (ECPs), and Engineering Change Notices (ECNs), and interface control Document control, including maintaining a Web-based system for finding and retrieving project data and utilizing the PPPL Ops Center		
Schedule:	See Attachment		
Approvals:			
	Job Manager	Date	
	Responsible Line Manager	Date	
	Project Manager	Date	
	Engineering Department Head	Date	