

EVERSON TESLA INCORPORATED

NCR # SC07052
NON CONFORMANCE REPORT

Part No: 53028 Description: APL Coil #4 PO/WO No: 933
 Supplier: ETI Date Rec'd: _____ Date Insp: 9/27/07
 Prepared By: R Brown Qty Rec'd: 1 Qty NC: 1

No	Requirement	AQL	SS	Qty	Describe Non-Conformance
	VPI Fill				Coil #4 - Areas of dry glass/ Air 12" wide - 4 FT Left of lead 16" wide - 3 FT Right of lead

Supplier Responsible? Yes No

Corrective Action Req'd? Yes No

Disposition: indicate qty

UAI	RTV	Screen
Rework	Scrap	Repair <input checked="" type="checkbox"/>

Customer Approval Req'd: Yes No

Customer Signature: M. Kim 10/2/07 P. Heitzman 10/3/07

Remarks: Wet lay-up .007" x 1.0" x 5" glass tape with CTD-540 resin in areas affected.

Approval:

Department	Signature	Date
ENGR.	<u>John Grapahl</u>	<u>9/27/07</u>
QA	<u>R. Brown</u>	<u>9/28/07</u>

Storerm			
Purch			
Prod Cntrl			

Original to be filed in QA

Verification Signature: _____ Date: _____

ETF021 Rev. 0 09/15/04