


TRC photos

23 July 2005


Clamp 16




Clamp 42




Clamp 46 Side A No Pad




More Side A




Side A Closeup




Side A




Side B Closeup



Side B




Side pad adjustment screw thread engagement



Swivel pad contact



Top pad closeup



Top pads

