PPPL NONCON	FORMANCE REPORT NO: 3664	Open D	ate 07/21/06	
Status	2 - Disposition Needed	Trend	05-Design Interferance	
Department	NCSX	Division	NCSX Project	
Source/Org	NCSX Project			
Item Dwg/Part#	SE120-004 R2 Pt.s 48 to 51, S Procurement	# D-NCS	C-FPA-QA1-00 Cost	Center
RAP# 3250	Job Doc # D-NCSX-FPA-QA1-00 Vendo	r		
RAP Title Field P	eriod Assembly Component Receipt Inspection			
HoldTag Applied				
Nonconforming	Condition (include requirement(s) violated	4):		
(VVSA-1, 2, 3) The t Bosses (pt.s 48 to 5 threading into the C	threads on the Vertical Support Clevises (pt. 1 Dwg. 1 Dwg. SE120-004 R2). Drawing SE124-051 R0 "\ levis Bosses. The Clevis Bosses are installed on the s well. The threads on each part are in accordance	g. SE124-055 /ertical Suppo le vacuum ves	rt Assembly" shows the visel (VVSA-1). This cond	Vertical Support Clevises
Vertical Support Clevis, 0.75 - 16 UNF threads, Qty. 12, pt. 1 Clevis Boss A, 0.75 - 10 UNC threads, Qty. 2, pt. 48 Clevis Boss B, 0.75 - 10 UNC threads, Qty. 2, pt. 49 Clevis Boss C, 0.50 - 13 UNC threads, Qty. 2, pt. 50 Clevis Boss D, 0.50 - 13 UNC threads, Qty. 2, pt. 51				
Lot Size Recd	0 Sample Size Insp 0	_	Lot Rejected	# Rejected
Reported By E	dwards J Validated By Phe	ps C	Validated	Date 07/21/06
For rework or repai	r of vendor supplied equipments, fill in informa	tion below:		Distribution
#Hours	\$Est Labor	\$G&A		Cog <u>M. Viola</u>
\$Material		\$Total		Insp Phelps/Boscoe
<b>aiviater iai</b>		φτυταί <u> </u>		Proj. Doc Control (when - closed)
Disposition By			Date	QC Files
Supervisor's Cor	ncur		Date	Malsbury J
Eng. Dept. Head		r	Date	Boscoe J Edwards J
WCO/Other			Date	Dudek L
		·		Malinowski F Reiersen W
				Williams M
PQA/QC Mgr Dis	pos Concur		Date	Tyrrell M
QC Field Verification By				
			Date	