

Coil	Wound/ VPI Comp	¹ Coil Post- VPI Items	² Initial Elect. Testing	Ground Poloidal Break	Final Clamps (incl short clamps)	T-Couples Installed (coil area)	Insul Installed	Bushing Fab	Premeasure Metrology	Location	New Holes	Grind/Mill (Nut Clearance)	Grinding (Overcast)	Comments
A-1	X	X	X	X	X	X	X	X	X	CFW		X	X	FPA
A-2	X	X	X	X	X	X	X	X	X	NCSX TC		X	X	3 PACK
A-3	X	X	X	X	X	X	X	X	X	NCSX TC		X	X	3 PACK
A-4	X	X	X	X	X	X	X		X	NCSX TC		X	X	3 PACK
A-5	X	X	X	X	X	X	X	X	X	CFW		X	X	3 PACK
A-6	X	X	X	X	X	X	X	X		CFW		X	X	3 PACK
B-1	X	X	X	X	X	X	X	X	X	CFW		X	X	FPA
B-2	X	X	X	X	X	X	X	X	X	NCSX TC		X	X	3 PACK
B-3	X	X	X	X	X	X	X	X	X	NCSX TC		X	X	3 PACK
B-4	X	X	X	X	X	X	X	X	X	NCSX TC		X	X	3 PACK
B-5	X	X	X	X	X	X	X			CFW		X	X	3 PACK
B-6	X	X	X	X	X	X	X			CFW		X	X	3 PACK
C-1	X	X	X	X	X	X	X	X	X	CFW	X	X	X	FPA
C-2	X	X	X	X	X	X	X	X	X	NCSX TC	X	X	X	3 PACK
C-3	X	X	X	X	X	X	X	X	X	NCSX TC	X	X	X	3 PACK
C-4	X	X	X	X	X	X	X			NCSX TC	X	X	X	3 PACK
C-5	X	X	X	X	X	X	X	X	X	CFW	X	X	X	3 PACK
C-6	X	X	X	X	X	X	X			CFW	X	X	X	3 PACK
	X	Done												Updated:
	IP	In Progress												10/15/2008 14:00:00 PM

Gross Fit	Completed (SAT)
C5-C1	10/26/2007
B1-C1	1/8/2008
A1-B1	11/27/2008
A1-A2	12/3/2007
A2-B2	2/5/2008
B2-C2	2/19/2008
C2-C3	1/15/2008
B3-C3	3/14/2008
A3-B3	3/11/2008
A3-A4	3/12/2008
A4-B4	4/14/2008
B4-C4	5/25/2008
C4-C6	
B5-C6	9/25/2008
A5-B5	9/23/2008
A5-A6	
A6-B6	10/13/2008
B6-C5	10/14/2008

¹ Diag box, loops, lock clamps etc.
² Includes hipot to 7.5 kV